

SL Tutorial

Removal of cured resin in SLA chamber

Tools needed:

high heat hair dryer or heat gun

sharp metal or plastic putty knife

Using the heat gun heat up the cured resin to be cleaned off

Scrape off soft cured resin with putty knife

By Bob Zubrickie

Disclaimer:

This is a suggestion only. The 3DSUG nor the submitter are liable for the actions or outcome of this suggestion.